Da(e:

Monday, 6/19/2006 11:30:51 AM

User:

Kim Johnston

**Process Sheet** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 27646

**Estimate Number** 

: 10176

P.O. Number

:NA

This Issue Prsht Rev. : 6/19/2006 : NC.

: NIA

S.O. No. : NA

: LARGE FAB ASSY Type

: 27404 **Previous Run** 

Written By

First Issue

Checked & Approved By Comment

Re-format Location RF

**Drawing Name** 

: STEP WELDMENT

Part Number

: D2563 : D2563 REV C

**Drawing Number** Project Number

: N/A

**Drawing Revision** Material

: 7/10/2006 Due Date

Qty:

2 Um:

Each

2

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

D2244116 1.0

Step Extrusion

Comment: Qty.: 1.0000 Each(s)/Unit Total:

2.0000 Each(s)

Pick:

D2244

Step Extrusion

Batch: 323404

D267334

End Plate

Comment: Qty.:

Pick:

2.0000 Each(s)/Unit Total:

4.0000 Each(s)

Qty Part No.

D2673-34

Description

2

End Cap

325396

3.0

2.0

D2561

Lug Plate



Comment: Qty.:

2.0000 Each(s)/Unit Total:

4.0000 Each(s)

Pick:

Qty Part No.

D2561

Description

2 D2564

Lug Plate

06.06.26

18.06.06.26

4.0

Comment: Qty.:

2.0000 Each(s)/Unit Total:

4.0000 Each(s)

Pick:

Qty Part No.

Description

Batch

D2564

Mounting Angle

325970

Page 1

Form: rprocess

## Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector						
							•						

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval Design Mgr	Approval			
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Section C		Approval QC Inspector			
								-			
				<b>*</b> ;	***						
				· •	-						
		· ·									

Part No:	PAR #:	Fault Category:		_ NCR: _Yes _ N	Jos DQA: _	 _ Date:	· · ·
NOTE: Date & initial all entries		•	# N	QA: N/	C Closed: _	 _ Date:	

Monday, 6/19/2006 11:30:51 AM User: Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: STEP WELDMENT** Job Number: 27646 Part Number: D2563 Job Number: Seq. #: Description: **Machine Or Operation:** LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Cut D2244 to 89.70" at 34° as per Dwg D2563 2-Deburr ends 2 3-Weld (1 End Only) as per Dwg D2563 using DT 8343 Batch: MIDOGGO A/R AL ROD 4-Grind WELD INSPECTION QC5/9 6.0 PD 06-06-27 Comment: WELD INSPECTION HAND FINISHING1 HAND FINISHING RÉSOURCE #1 مر7.0 Comment: HAND FINISHING RESOURCE #1 INSPECT POWDER COATIONEMICAL CONVERSION Chemical Conversion Coat as per QSI 005 4.1 8.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION LARGE FABRICATION RESOURCE 1 **Comment: LARGE FABRICATION RESOURCE 1** 18.06.06.28 1-Inspect for foreign object per QSI 024 1. 2. 06.06 -28 2-Weld Remainig End as per Dwg D2563 using DT 8343 A/R AL ROD Batch: M100660 FF 06.06. 3-Grind QC5/9 WELD INSPECTION 10.0 **Comment: WELD INSPECTION** 

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector				
			•	3							
			•	_							
					: !						
			٠.								
,											

NCR:		V	WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Verification	Annroval						
DATE	STEP	Section A	Initial Action Description Sign & Design Mgr Date			Section C	Approval Design Mgr	Approval QC Inspector					
		·											
			·										
			·										

Part No:	PAR #:	Fault Category:	NCR:	Yes No DQA:	Date: 06/07/07
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

Date: Monday, 6/19/2006 11:30:51 AM User: Kim Johnston **Process Sheet** 0208-633-021 Drawing Name: STEP WELDMENT Customer: CU-DAR001 Dart Helicopters Services Job Number: 27646 Part Number: D2563 Job Number: Seq. #: Description: **Machine Or Operation:** POWDER COATING POWDER COATING 11.0 Comment: POWDER COATING 06.06.29 2 Touch up Alodine then Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 HAND FINISHING1 HAND FINISHING RESOURCE #1 12.0 Comment: HAND FINISHING RESOURCE #1 07 04 Wing Walk as per Dwg D2563 and QSI 005 4.4 13.0 INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION DOCUMENT CONTROL 14.0 DC Comment: DOCUMENT CONTROL Inspection Level 21 U 06-07-07 Job Completion

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector				
		· · · · · · · · · · · · · · · · · · ·									

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
<del></del>	T	Description of NC		Corrective Action Section B		Varification	Approval Design Mgr					
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Verification Section C		Approval QC Inspector				
				•								
								-				
							. 4 - 2					

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: I	N/C C	losed:	Date:

